

.....

630 Valley Mall Parkway #233  
East Wenatchee, WA 98802  
509)667-8111

# Tryways, Inc.

September 22, 2021

Dan Bigos  
2810 Akamai Way  
East Wenatchee, WA 98802

RE: Aspen Shores RIRDFS Inspection 2021

### Drain Field Summary:

System #1	Pump #1	Pump#2	Solids Measured	Float/Alarms/Filters
Cycles	11736	12422	0"	O.K.
Run Time	18235	553		
System #2	54559	54462	0"	O.K.
	1206	952		
System #3	10876	10700	0"	O.K.
	956	896		
System #4	16951	17596	0"	O.K.
	239	162		
System #5	2931	2958	0"	O.K.
	99	98		
System #6	19484	18631	0"	O.K.
	921	1455		

.....

September 22, 2021

Page 2

System #1, has an electrical cord grip that is broken on the splice box and this needs to be replaced as soon as possible. System #2 has two (2) cord grips on the electrical splice box that is broken and needs replaced. System #3 has the top three (3) floats that are cracked and should be replaced. They are working properly at this time but need to be addressed. The first drain field area in system #3 with the orange marked lateral did not have water come out when tested. It was coming through the alternating valve but never reached either ends of the lateral. Dan Bigos was informed during his site visit. Drain field # 5 & #6 has had a lot of water being the low point of the orchard along with tractor traffic. No standing water was present during this inspection. System #6 has a broken electrical cord grip and should be replaced. All the systems floats, pumps and alarms were working properly at the time of this inspection. Keyhole Security was notified to allow alarms until 5:00 p.m. on Thursday 9.22.21. Any alarms after this would need to be addressed.

Sincerely,

A handwritten signature in black ink, appearing to read 'Eric Stanaway', written over a horizontal line.

Eric Stanaway